

## Message Text

LIMITED OFFICIAL USE

PAGE 01 OUAGAD 02841 030721Z  
ACTION SY-05

INFO OCT-01 AF-10 ISO-00 /016 W  
-----008188 030734Z /17

P R 301631Z JUN 78  
FM AMEMBASSY OUAGADOUGOU  
TO AMEMBASSY ABIDJAN PRIORITY  
INFO SECSTATE WASHDC 7435

LIMITED OFFICIAL USE OUAGADOUGOU 2841

FOR RSO

E.O. 11652: NA  
TAGS: ASEC  
SUBJECT: LOCK MALFUNCTION

HAD S&G LOCK (GROUP ONE) MALFUNCTION ON FRONT DOOR OF EMBASSY.  
TENSION SPRING ON DRIVE CAM BROKEN WHICH WOULD NOT ALLOW TUMBLER  
TO WORK PROPERLY. UPON REPLACEMENT OF DRIVE CAM, LOCK WORKS  
PROPERLY. REQUEST REPLACEMENT OF DRIVE CAM. SORRY THERE APPEARS TO  
BE NO MODEL NUMBER THAT CAN BE SEEN. KILLION

NOTE BY OC/T: TELEGRAM DELAYED IN TRANSMISSION.

LIMITED OFFICIAL USE

NNN

## Message Attributes

**Automatic Decaptioning:** X  
**Capture Date:** 01 jan 1994  
**Channel Indicators:** n/a  
**Current Classification:** UNCLASSIFIED  
**Concepts:** n/a  
**Control Number:** n/a  
**Copy:** SINGLE  
**Draft Date:** 30 jun 1978  
**Decaption Date:** 01 jan 1960  
**Decaption Note:**  
**Disposition Action:** RELEASED  
**Disposition Approved on Date:**  
**Disposition Case Number:** n/a  
**Disposition Comment:** 25 YEAR REVIEW  
**Disposition Date:** 20 Mar 2014  
**Disposition Event:**  
**Disposition History:** n/a  
**Disposition Reason:**  
**Disposition Remarks:**  
**Document Number:** 1978OUAGAD02841  
**Document Source:** CORE  
**Document Unique ID:** 00  
**Drafter:** n/a  
**Enclosure:** n/a  
**Executive Order:** N/A  
**Errors:** N/A  
**Expiration:**  
**Film Number:** D780273-0945  
**Format:** TEL  
**From:** OUAGADOUGOU  
**Handling Restrictions:** n/a  
**Image Path:**  
**ISecure:** 1  
**Legacy Key:** link1978/newtext/t1978063/aaaaacgt.tel  
**Line Count:** 37  
**Litigation Code IDs:**  
**Litigation Codes:**  
**Litigation History:**  
**Locator:** TEXT ON-LINE, ON MICROFILM  
**Message ID:** 49203a83-c288-dd11-92da-001cc4696bcc  
**Office:** ACTION SY  
**Original Classification:** LIMITED OFFICIAL USE  
**Original Handling Restrictions:** n/a  
**Original Previous Classification:** n/a  
**Original Previous Handling Restrictions:** n/a  
**Page Count:** 1  
**Previous Channel Indicators:** n/a  
**Previous Classification:** LIMITED OFFICIAL USE  
**Previous Handling Restrictions:** n/a  
**Reference:** n/a  
**Retention:** 0  
**Review Action:** RELEASED, APPROVED  
**Review Content Flags:**  
**Review Date:** 22 apr 2005  
**Review Event:**  
**Review Exemptions:** n/a  
**Review Media Identifier:**  
**Review Release Date:** n/a  
**Review Release Event:** n/a  
**Review Transfer Date:**  
**Review Withdrawn Fields:** n/a  
**SAS ID:** 2242927  
**Secure:** OPEN  
**Status:** NATIVE  
**Subject:** LOCK MALFUNCTION HAD S&G LOCK (GROUP ONE) MALFUNCTION ON FRONT DOOR OF EMBASSY. TENSION SPRING ON DRIVE CAM BROKEN WHICH WOULD NOT  
**TAGS:** ASEC  
**To:** ABIDJAN  
**Type:** TE  
**vdkgvkey:** odb://SAS/SAS.dbo.SAS\_Docs/49203a83-c288-dd11-92da-001cc4696bcc  
**Review Markings:**  
Sheryl P. Walter  
Declassified/Released  
US Department of State  
EO Systematic Review  
20 Mar 2014  
**Markings:** Sheryl P. Walter Declassified/Released US Department of State EO Systematic Review 20 Mar 2014